



## Weighing Indicator XK3190-A7



### Feature

A/D conversion speed with max external counts 15000(without division switch) 7500 (with)

Use inner code to replace weight observing for analyzing the tolerance.

Zero tracking range, Zero range and Zero speed adjustment function

Indicate the battery volume or status

Protect the low battery

Optional function: 1.Kg/Lb. switch

### Parameters

Model	A7	A7+
Input signal range	0mV~16mV	
Input sensitivity	≥1μV/e	
Load cell Excitation	Dc 8V:≤150mA	
Max. load cell connection	1 at 350 ohm	4 at 350 ohm
Display	6 bits LED, 6 status indications	
Optional interface	RS232C serial communication	
Transmission distance	RS232C≤30 meters	
Power supply	AC 187-242V 49-51Hz, DC 12V 8AH	
Product weight	15.5KG	